

### MISSOURI DEPARTMENT OF HEALTH STATE PUBLIC HEALTH LABORATORY

**DATAMASTER MAINTENANCE REPORT** 

RECEIVED COST Profe States (Program By Carol Day at 12:20 pm, Mar 09, 2010

Complete this report in duplicate at the time of the re is repaired. Send copy to Department of Health; retain or		ance check, and whenever instrument
DATAMASTER SN 204108		DATE OF INSPECTION 3-1-10
LOCATION OF INSTRUMENT (STREET AND CITY)	40.62460	TIME OF INSPECTION
Ralls Co. Sheriffs Dept., 301 Ralls St., New London, I CHECKLIST: Place a check ( ) to the left of each item		orating within established limits. (Write
in observed values where determined.) Unchecked items		
D DIAGNOSTIC CHECK (PRINTOUT ATTACHED)		
☑ COMPUTER	☑ DETECTOR	٤'
☑ PROGRAM	☑ FILTERS	
☐ HEATERS SAMPLE CHAMBER °C	☑ QUARTZ STANDARD	
☑ FLOW DETECTOR	☑ CALIBRATION	
🛮 PUMP HIGH SPEED	PRINTER	
☑ INDICATOR LIGHTS		
☑ TIME AND DATE		
☑ SIMULATOR TEMPERATURE (34 °C ± 0.2°C)		
☑ CALIBRATION CHECK -		
Run three tests using a standard solution. All three		
spread of .005 or less. Check the box corresponding RECIRCULATION PUMP)	g to the standard solution being t	ised. (PHINTOUT ATTACHED) (USE
0.100% STANDARD - MUST READ BETWEEN 0.0		,
		ST3 🚩 🚜 G
	. 098 TE	ST 3 - , C9°;
PERFORM R.F.I. TEST (PRINTOUT ATTACHED)		
NUMBER OF REFUSALS, SINCE LAST MAINTENANGE FOLLOWS: (DO NOT INCLUDE SIMULATOR TEST		REATH TESTS IN EACH RANGE AS
REFUSALS (004) (.0509)	) (.1014) / (.15	19) / (Over .19) <i>(</i>
List any new parts and describe any alteration or modifi	cation that was made t: restore th	e instrument to operate satisfactorily
and within established limits (use other side if necessary)		and the second s
		***************************************
Instrument meets Dept. of Health specs., RepCo Mark	teting Inc., .10 solution, lot no. 978	202, exp. de-31-11
INSPECTING OFFICER SIGNATURE	PRINT NAME	
B. C. Hullis	B. C. Griffin	
TYPE II PERMIT NUMBER/EXPIRATION DATE!	(660) 385-2132	
	1(000) 303-2135	

3101-188 STONYBROOK DRIVE RALEIGH, N.C. 27604 919-876-5480

### **CERTIFICATE OF ANALYSIS**

MANUFACTURER AND SUPPLIER: RepCo Marketing, Inc.

LOT NUMBER: 09002

EXPIRATION DATE: August 31, 2011 at 11:59 p.m.

RepCo Marketing, Inc. certifies the following:

RepCo Marketing, Inc. manufactured, tested and supplied Lot Number <u>09002</u> of Alcohol Certified Solution for simulators. Random samples of said lot number were analyzed by an independent laboratory utilizing a gas chromatograph and found to contain <u>.1206</u> gms/dl +/-.003 gms/dl wt/vol ethanol (95% Confidence).

The alcohol and distilled water used in the solution were found to be free of any interfering substance.

This solution will produce a vapor alcohol value of <u>.100</u> +/-3% gms/210L Breath when heated to 34 Degrees Celsius +/-0.2 Degrees Celsius in a simulator (95% Confidence).

The date of manufacture for this lot number is <u>September 1, 2009.</u>

The expiration date for this lot number is <u>August 31, 2011</u> at 11:59 p.m.

This document is a true representation of the original Certificate of Analysis.

Cecil B. Garner, President RepCo Marking, Inc.

### State of Missouri DEPARTMENT OF HEALTH



MO 580-0771 (7-88)

### PERMIT TYPE II



Lab. 4 (R7-88)

#### **BRANDON C GRIFFIN**

DATAMASTER

is hereby authorized to instruct and supervise operators, train instructors, inspect, calibrate, perform field repairs, and operate the following breath analyzer(s):

### 

## **BAC DataMaster**Evidence Ticket

MISSOURI STATE MIGHWAY PATROL BAC DATAMASTER SERIAL MUMDER 204108 03/01/10

TESTING OFFICER:

GRIFFIN/B/C

OFFICER I.D.: 0429

PERMIT NUMBER: 20033 B.C.6.

EXPIRATION DATE: 02-05-2012

MINCELLANEOUS DATA:

--- SUPERVISUR MODE ---

BLANK TEST	, GØÐ	1.01.34
INTERMAL STANDARD	VERIFIED	19:34
EXTERNAL STAMDAKD	.097	10:35
BLANK TEST	. 996	19:36
EXTERNAL STANDARD	. 692	10:36
BLANK TEST	. Girifi	10:37
EXTERNAL STANDARD	.099	10:37
BLANK TEST	. 898	10:38

N = 3 SIM. = .1 AVS. = .098

### Face This Side Down - This Edge In First

## **BAC DataMaster**Evidence Ticket

MISSOURI STATE HIGHWAY PATROL BAC DATAMASTER SERIAL MUMBER 204108 03/01/10 10:18

--- DIAGNOSTIC CHECK ---

OKAY COMPUTERS PROGRAM (04-07-2009): OKRY HEATERS SAMPLE CHAMBER: 49c FLOW DETECTORS OKHY FUMP OKAY HIGH SPEEDS OKAY DETECTORS OKRY' FILTERSA QUARTZ STAMBARDS OKMY CALIBRATION: OKSY

PRINTER TEST
:"#\$%%:()\*+,-./0123456789:;(=)?@FRCDEFG
HJUKLMHOPQRSTUVWXYZ[\]^\_'abcdefghijklmno

parstuvwajz(1)+~

Operator Signature 3. 4.

Operator Signature\_

2208

B. C. Anf

2208-0

#### Face This Side Down - This Edge In First

# **BAC DataMaster**Evidence Ticket

MISSOURI STATE HIGHWAY PATROL BAC DATAMASTER SERIAL NUMBER 204108 63/01/10

ARREST TIME: 09:00 SUBJECT MAKE: TEST DOB: 01/01/70 SEX: M STATE/D.L.: MO/1234567890 ARRESTING OFFICER: SRIFFIHZBZC OFFICER I.D.: 0429 TESTING OFFICER: GRIFFIM/B/C OFFICER 1.D.: 0429 B.C.6. PERMIT MUMBER: 20033 EXPIRATION DATE: 02-15-2012 MISCELLAMEGUS BATA: R.F.I. TEST

--- BREATH AMOLYSIS ---

BLANK TEST / INTERNAL STANDARD RADIO INTERFERENCE .000 10:42 VERIFIED 10:42

Operator Signature

2208-02